

FIG. 5




FIG. 6




FIG. 7




FIG. 8





Scanner	Scanner Function A			Printer
000	• ID:	1:1 [Conv	ersion: Color→Gray]	
	Version:	1.00.0	00	
	Name:	"Color/Gray conversion"		
	• Purpose:	"Converts 24 bit color images to 8 bit gray scale images."		
	 Processing Cost: 		5 second operation anner]	-
	• Size:	64K		
	• Exportable:	Yes:	Platform Dependent	<u> </u>
ij cañãer Function B			Scanner Function C • ID: 6:6 [Decompression:	
ID <u>:</u>	1:2 [Conversion: Gray→	B&W]	• 1D.	JPEG]
Version:	3.00.00		• Version:	1.10.09
Name:	"Gray/B&W convers	sion"	Name:	"JPEG"
Purpose:	"Converts 8 bit colo images to black and images."	or I white	• Purpose:	"Decompress images best for color photographs. Note that it is a lossy scheme!
 Processing Cost 	t: 12 [12 second operat scanner]	ration	Processing Cost:	20 [20 second operation at scanner]
• Size:	85K		• Size:	90K
• Exportable:	Yes: Platform Independent		Exportable:	No

FIG. 9A





Scanner	Printer Function A		Printer
the first that the first the first that the first t	• ID:	1:2 [Conversion: Gray→B&W]	
	Version:	2.00.23	
	Name:	"Gray/B&W conversion"	
	Purpose:	"Converts 8 bit color images to black and white images."	
	Processing Cost:	10 [10 second operation at printer}	
	• Size:	40KB	
	Exportable:	No	
	Printer Function B		
	• ID:	5:9 [Compression & Decompression: JPEGLS]	
	• Version:	1.10.09	
	• Name:	"JPEG-LS"	
	• Purpose:	"Compress images - best for color photographs. Note that it is a loss-less scheme!"	
	Processing Cost:	25 [25 second operation at printer]	
	• Size:	100KB	
	Exportable:	Yes: Platform Independent	

FIG. 9B




FIG. 10